



NGK Spark Plug - ILFR5B11

RN1637



Replaces

Bosch	FR8MII33X
-------	-----------

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Krima Trading AB

Stene 710 Kumla, 692 93

+46 19 57 35 20

<https://krima.rrproducts.com/>