




Repair Kit - Bed Bar

R150530



Details

Includes 20 ea: R150531 Insert; 1 ea: R150532 Drill, R150533 Tap

Specifications

Manufacturer R&R Products

Fits Models

Toro Reelmaster 335D
Toro Reelmaster 3500-D
Toro Reelmaster 4000-D
Toro Reelmaster 4500D
Toro Reelmaster 450-D

Replacement Parts

R150531	Insert - 1/2-20
R150532	Drill - 21/32
R150533	Tap - 3/4-10

Krima Trading AB

Stene 710 Kumla, 692 93

+46 19 57 35 20

<https://krima.rrproducts.com/>