


Replaces Toro Greensmaster 3150-Q Parts



SPA Cutting Unit - Models 04460, 04465, 04468 & 04478 Minuteman Roller System





Replaces Toro Greensmaster 3150-Q Parts



SPA Cutting Unit - Models 04460, 04465, 04468 & 04478 Minuteman Roller System

	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity		
Comp	olete Minutemo	an Roller Systems					
1	RMT8001		Minuteman Front Grooved Roller System	0			
	Tech Note: Con	mplete roller systems i	include roller and two brackets with bearings.:				
Minu	teman Rollers	Only					
2	RM513		Minuteman Grooved Roller Only	0			
	Tech Note: Use with Minuteman Roller Bracket System Only:						
Othe	r Parts Availab	le					
3	RT821		Bracket Assy - Front LH/RH	2			
	Tech Note: Includes RT8210 Bearing & Locking Collar, RMM606 Washer, R3219-5 Nut & RMM607 Screw:						
4	RMMB157		Bearing w/Locking Collar	2			
5	RT8210		Block - Height Adj	2			
6	RMM606		Washer - Lock 3/8 Zinc Internal Tooth	2			
7	R3219-5	01-188-0820, 22-15-BJD, 22-15-BJKD, 3219-5	Nut - 1/2-20	4			
8	RMM607	01-158-0610, 01-191-0820, 21-3900, 3220-5, 45-0170, 5/1/3220	Nut - Jam 1/2-20 Zinc	2			
9	RMM608		Screw - 8-32 x 5/16 SS Socket Head	2			
10	RMM3		End Hub - 7/8 ID	2			
11	RT821P		Plate - For RT821 Bracket	2			

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Greensmaster 3150-Q Parts



SPA Cutting Unit - Models 04460, 04465, 04468 & 04478 Minuteman Roller System

Item R&R	OEM	Description	Qty	Order
No Part No.	Part No.		Req	Quantity
12 RT821B		Ball - For RT821 Bracket	2	