

## **2-1/2,3 Viton T/U Ball Valve Repair** RGTUVRK030





Repair Kits

## **Details**

Ball Valve Kit includes: 2-PTFE Seats, 2-Seat O-rings (2-1/2"), 2-End Connector O-rings, 1-Stem Bearing (1-1/4" & up).

## **Specifications**

Manufacturer Spears
Manufacturer's TU-VRK-030

Model No

Seal Type Viton

**Krima Trading AB**Stene 710 Kumla, 692 93
+46 19 57 35 20